

RECALL NOTICE

RECALL TO REPAIR POWERSMART 2-STAGE GAS SNOW BLOWERS

PowerSmart Gas Powered 2-Stage Snowblowers sold
between mid 2016 – Feb 2018

Models DB7651-24, DB7659H-22, DB7659-22, DB7103-27

Loose pulley bolt can loosen and cause the machine to get
stuck in drive mode, posing an injury hazard



**Stop using the snow blowers immediately
and contact Amerisun for inspection
instructions and free repair kit**

For more information:

877-791-9458 from 8:00 am to 5:00 pm ET Mon – Fri or

www.powersmartusa.com