

Safety Recall Notice

BLACK+DECKER™ BV5600, BV6000 and BV6600 Electric Blower/Vacuum/Mulchers

The fan cover can unlatch unexpectedly, posing a laceration hazard.

Affected Models and Types

BV5600, Type 1

BV6000, Type 1

BV6600, Type 1

Only blower vacs with the model numbers and types above are affected. Type 2 models are not affected. The model number and type are on a label on the right side of the motor housing (see below).



Location of Model
Number and Type



Recalled Fan
Cover



Replacement
Fan Cover

If your product is included, **STOP USING IT IMMEDIATELY**
and call BLACK+DECKER toll free

1-866-937-9805

between 8:00 a.m. and 5:00 p.m., Eastern Time, Monday through Friday or email recall@sbdinc.com to arrange for a free replacement fan cover. For more information log on to BLACK+DECKER's web site at www.blackanddecker.com.