

IMPORTANT SAFETY NOTICE

ONE WORLD TECHNOLOGIES, INC. RECALLS RYOBI 40-VOLT BRUSHLESS SNOW BLOWER



The snow blowers can overheat, posing a fire and burn hazard.

Only Ryobi 40-Volt Brushless Snow Blowers sold between August 2015 and February 2016 and bearing model numbers RY40802 are included in the recall.

Consumers should *immediately* discontinue use of their 40-Volt Brushless Snow Blower and contact One World Technologies for a full refund.

If you have any questions or require additional information, please contact One World Technologies, Inc. Customer Service at

1-800-597-9624 or visit www.ryobitools.com