URGENT RECALL NOTICE

For details refer to the following link issued by Health Canada: https://recalls-rappels.canada.ca/en/alert-recall/makita-18v-cordless-grease-gun-and-certain-makita-flexible-hoses-recalled-due

Makita Canada Inc, Announces Recall Of MAKITA Brand DGP180 18V Cordless Grease Gun And Flexible Hoses For Grease Gun





Hazard: When the grease gun is pumping grease, and the hose is bent near the adapter; a hole can be created in the hose, and it may burst near the adaptor end of the hose. This may pose a laceration hazard to the operator.

Recalled Product:

Product	Model	UPC
18V Cordless Grease Gun	DGP180Z	0 88381 88681 9
18V Cordless Grease Gun	DGP180SYX1	0 88381 75246 6
18V Cordless Grease Gun	DGP180YEX1	0 88381 75247 3
18V Cordless Grease Gun	DLX2465TX1	0 88381 75245 9

Product	Model	UPC
Flexible Hose 600 mm	191A80-4	0 88381 55851 8
Flexible Hose 600 mm	191W59-7	0 88381 58534 7
Flexible Hose 1200 mm	191W58-9	0 88381 58533 0

Grease Gun

Makita brand 18V Cordless Grease Gun with model number DGP180Z (UPC 0 88381 88681 9) and includes ALL TOOLS IMPORTED TO CANADA TO DATE (up to and including February 2025).

This tool may also be a component of the following kits: DGP180SYX1 (UPC 0 88381 75246 6), DGP180YEX1 (UPC 0 88381 75245 9)

The 18V Cordless Grease Gun has a teal/black plastic housing with a machined, aluminum front housing and an aluminum cylinder directly under the teal/black housing and is described as an 18V LXT Grease Gun.

The overall product length is 41.1 cm. and weighs 3.5 kg.

Affected products will have a serial number between 11291 and 221391.

Flexible Hose

Makita Canada is also recalling items 191A80-4 600 mm flexible hose (UPC 0 88381 55851 8); 191W59-7 600 mm flexible hose (UPC 0 88381 58534 7) and 191W58-9 1200 mm flexible hose (UPC 0 88381 58533 0).

The flexible hoses have a black rubber body with a silver threaded coupling on one end and a silver adapter on the other end

The length of items 191A80-4 & 191W59-7 is 600 millimetres in length and item 191W58-9 is 1200 millimetres in length. The hoses do not have serial numbers.

Return: Consumers should stop using these products immediately and contact Makita Canada, Inc. to schedule a FREE REPAIR.

For More Information:

1 800-663-0909

(Western Canada)

Hours: Mon – Fri, 8 a.m. – 4:30 p.m. (PST)

www.makita.ca

1 800-263-3734

(Eastern Canada & Prairies)

Hours: Mon - Fri, 8 a.m. - 4:30 p.m. (EST)

www.makita.ca

Distributed by Makita Canada Inc, Whitby, Ontario, CANADA; Manufacturer: Makita (China/Kunshan) Co. Ltd., CHINA