

SAFETY RECALL

JOHN DEERE D110, D125, D130, D140, D155, D160 and D170 LAWN TRACTORS



PROBLEM: The brake arm on the transmission in your lawn tractor may not have been manufactured to specification and could fail. If this occurs, the lawn tractor loses mechanical braking and the parking brake function. This creates a risk of a crash, which could result in serious injury or death.

PRODUCT: Some John Deere model D110, D125, D130, D140, D155, D160 and D170 lawn tractors, manufactured between 25 May 2015 and 13 June 2015. A complete list of serial numbers included in this recall is located at www.JohnDeere.com/D100SeriesLawnTractorBrakeArmRecall

Remedy: Consumers should stop using the recalled lawn tractors immediately and contact a John Deere dealer for a free repair. John Deere is contacting all registered owners of the recalled lawn tractors directly.

FOR FURTHER INFORMATION CONTACT Deere & Company at (800) 537-8233 Monday through Friday from 8 a.m. to 6 p.m. and on Saturdays from 9 a.m. to 3 p.m. ET or visit the firm's Web site at www.johndeere.com.

Post until: 31 December 2015

In cooperation with the U.S. Consumer Production Safety Commission and Health Canada